
| PICKWP Ta | nk Repair Shop at Neubra | denburg | e. Main Parintelliministration entitionis dissipantisminis included a rel m. inc. 700 Julius wishing |
|---------------|--|--|---|
| ALUATION | PLACE (| DRTAINEE | 638739 _{25X} |
| TE OF CONTENT | | 75 TAIN | enti-militari marcado d'inimican interpretable de abblica conserva. Est cas a appare |
| TE OFTAINED | | DATE_PREPARED30 | June 1954 |
| FERENCES | | WIE FRECHNED | nink andatanamininka staratenia danistranaminin suntaninka suvus ini idasin umusik 1900-yili 1905-yili 1900-yili 1905-yili |
| CES | ENCLOSURES (NO. & TYPE) | 1 - sketch on ditto | 25X1 |
| | | | edit editalli philiophilise and the end of the edital behind the edital and an edital |
| PARKS | This is UNEVALUATED | era de managamente de este esta per esta per esta de la companya d | 25X1 |
| 7.7 | The state of the s | teritorio de la compansión de la constitución de la constitución de la constitución de la constitución de la c | ent vilkatataanan ahaalina vartaahabatki (1946-1946), s 467-1944 sakki (|
| | | - | 25X1 |

- In mid-May 1954, about 1,000 workmen were employed at the KVP tank repair shap at Heubrandenburg. Since enlargement of the installation was not completed, the bank repair shop had not reached its full capacity. Since the beginning of 1954, 10 to 16 used Soviet armored vehicles have been overhauled monthly. A shortage of spare parts many of which had to be manufactured in a makeshift way at the repair shop, delayed repair work. Courses for tank drivers, tank mechanics, and assistant armorer-artifice is have been held at the repair shop for some time. The KVP main depot for tank share parts is allegedly located at Finow.
- 2. In April, about 1,200 workmen, including construction workers, were employed at the KVP tank repair shop at Neubrandenburg. Deliveries made in April included 10 to 12 tanks. In mid-April, 30 to 40 tanks in need of repair were at the installation. The first course for KVP personnel terminated in mid-March. They were only 30 KVPs in attendance at that second course.
- In March, incoming shipments at the KVF teak repair shop at Neubrandenburg included 7 T=34/76, 6 T=34/85, 6 SU-76 and 2 SU-85 Between 1 and 23 April, another 6 T=34/85 and 5 SU-76 arrived at the installation, but, between 23 April and 17 May, no incoming armored vehicles were seen, Armored vehicles in need of repair numbered 33 on 15 March; 37 on 15 April; and 41 on 15 May. Since spare parts and wire for arrature windings were not available, the repair of the radio equipment was rather difficult. Some of the used radio sets had to be cannibalized in order to obtain parts for the repair of other equipment. From early April to mid-May, approximately 14 evertabled armored vehicles had to be delivered without radio equipment. Materials and presisting tools were still in short supply. In mid-April, nine armored vehicles were delivered to Eggesin and Potsdam, Main deficiencies observed with the vehicles turned in serve worm out floating axles, tracks, and track pins. Many engines also were in mesh of repair. Most of the axles were re-welded and newly turned and only few of their serve replaced. Tracks and track pins were replaced; unrepairable engines were also replaced. Radio and optical equipment was also in need of repair. In mid-May, about 800 workmen were engaled in repair work.

25X1

O PER PATRON. SEET F



SECRET,

25X1

SECRET

⇔ 2 æ

egenda.

- Administration building
- 2 New workshop which was to be finished by 1 May 195%
- A Reconstructed building. The mechanical department seved to the garage item No 21. Building A was vacant.
- 5 Workshop. After completion of workshop item No 2, the building will be demolished
- 6 = Hall containing the gear making, elements, and sadilars depretaring and the radio repair shop
- 7 Hall containing the tool wop, and wheel-wounting shop
- 8 Building under reconstruction; southern portion was completed
- 30 = Forge and welding shop
- 14 Warehouse
- 15 New warehouse
- 16 Building similar to the varkshop item No 5 under construction
- 17 Bunker, purpose undetermined
- 16 laboratory
- 19 Kitchen building
- 20 Small garage for refilling compressed air containers
- 21 Garage for motor vehicles. The building also contained the mechanical department
- 22 Heating plant
- 23 Railroad ramp (in need of repair)
- 24 Wooden watch towers, not occupied

The railroad siding was extended about as far as lake Tollease; a sper urnar extended from the siding to the samp heads

SECRET